

2003 Pontiac Vibe Base 1.8L 4Cyl GAS 1ZZ-FE Naturally Aspirated

RO # 6670

Odometer In: 184803 / Out: 184803

Client Concerns

Vibration when in gear

High pitched sound accelerating

Inspection Rating Key:

☺ Checked & Okay ⚠ Requires Attention Soon ✖ Requires Immediate Attention — Not Applicable

COURTESY INSPECTION

TECH: [REDACTED]

☺ ⚠ ✖ — BATTERY TEST

☒ ☐ ☐ ☐ BATTERY TEST

Finding:

☺ ⚠ ✖ — AIR FILTER

☐ ☒ ☐ ☐ Air Filter

Finding:



☺ ⚠ ✖ — COOLANT

☒ ☐ ☐ ☐ COOLANT

Finding:

☺ ⚠ ✖ — BRAKE FLUID

☒ ☐ ☐ ☐ Brake Fluid Condition

Finding:

☺ ⚠ ✖ — POWER STEERING FLUID


☒ ☐ ☐ ☐ Power Steering Fluid Condition

Finding:

☺ ⚠ ✖ — SERPENTINE BELT

☐ ☐ ☒ ☐ Belt Condition

Finding: Bad tensioner



☺ ⚠ ✖ — FLUID LEAKS

☐ ☐ ☒ ☐ Leaks

Finding: 4 coils Valve cover gasket



☺ ⚠ ✖ — CABIN FILTER

☐ ☐ ☒ ☐ Cabin Filter Condition

Finding:



☺ ⚠ ✖ — SUSPENSION

☐ ☐ ☒ ☐ FRONT

Finding: Struts Steering rack



☺ ⚠ ✖ — CV AXLES

☐ ☐ ☒ ☐ CV AXLE

Finding:



☺ ⚠ ✖ — FRONT BRAKES

☐ ☐ ☒ ☐ Front Brakes Condition	Finding: 5 mm
	
😊 ⚠️ ✖ — FRONT TIRES	
☒ ☐ ☐ ☐ Front Tires Condition	Finding:
😊 ⚠️ ✖ — SUSPENSION	
☐ ☐ ☒ ☐ REAR	Finding: Struts Subframe corrosion
	
😊 ⚠️ ✖ — REAR BRAKES	
☐ ☒ ☐ ☐ Rear Brakes Condition	Finding: Clean adjust
😊 ⚠️ ✖ — REAR TIRES	
☒ ☐ ☐ ☐ Rear Tires Condition	Finding:
😊 ⚠️ ✖ — STATE INSPECTION REPORT PHOTO	
☒ ☐ ☐ ☐ STATE INSPECTION REPORT PHOTO	Finding:

***VEHICLE CHECK IN PHOTOS		TECH: [REDACTED]
😊 ⚠️ ✖ — WALK AROUND VIDEO /INTERIOR/ DOOR PLACARD TIRES+VIN/ ***MILEAGE PHOTO		
☐ ☐ ☒ ☐ WALK AROUND VIDEO /INTERIOR/ DOOR PLACARD TIRES+VIN/ ***MILEAGE PHOTO	Finding: Coils Spark plugs Evap code	
		